Message Text

UNCLASSIFIED

PAGE 01 MASERU 00091 111455Z POSS DUPE ACTION SY-05

INFO OCT-01 AF-10 ISO-00 SYE-00 SSO-00 OC-06 CCO-00 OCPE-00 /022 W

-----117456 111516Z /46

O R 111440Z JAN 78 FM AMEMBASSY MASERU TO SECSTATE WASHDC IMMEDIATE 8029 INFO AMEMBASSY ACCRA AMEMBASSY NAIROBI AMEMBASSY PRETORIA

UNCLAS MASERU 0091

STATE FOR A/SY/NSU; OC/PE

ACCRA FOR COMSPEC

NAIROBI FOR RCO; RSS

PRETORIA RSO; OIC TSO, CPOIC SEABEE TEAM

E.O. 11652: N/A

TAGS: AFAC, ASEC, NSU, ABLD, LT SUBJECT: STEEL PLATING OF TELEX RM

REF: STATE 005368

- 1. FOLLOWING INFO PROVIDED IN RESPONSE TO REFTEL.
- A. MATERIAL CAN BE ON SITE THREE (3) WEEKS AFTER ORDERING.
- B. ALL EQUIPMENT IS AVAILABLE (I.E. WELDER, GAS CUTTING TORCH AND WELDING ROD)
- 2. THREE EIGHTHS INCH STEEL PLATING WILL HAVE TO BE USED AS LOW CARBON HIGH TENSILE STEEL IS NOT AVAILABLE.
- 3. ARCHITECT OF ORIGINAL BUILDING INFORMS US THAT ROOF UNCLASSIFIED

UNCLASSIFIED

PAGE 02 MASERU 00091 111455Z POSS DUPE

AND REBAR OVER THE REST OF THE BUILDING IS THE SAME AS OVER THE EXISTING VAULT. POST THEREFORE DOES NOT CONSIDER IT NECESSARY TO STEEL PLATE CEILING.

4. FYI. THE CONTRACTOR INFORMS US THAT THE COST OF THE MATERIAL NEEDED WILL BE AROUND 4000 DILLARS U.S. PLEASE ADVISE ASAP WHETHER TO GO AHEAD AND IF SO SUPPLY

APPROPRIATE ACCOUNTING DATA. STOKES

UNCLASSIFIED

NNN

Message Attributes

Automatic Decaptioning: X Capture Date: 01 jan 1994 Channel Indicators: n/a

Current Classification: UNCLASSIFIED

Concepts: n/a Control Number: n/a Copy: SINGLE Draft Date: 11 jan 1978 Decaption Date: 01 jan 1960 Decaption Note: Disposition Action: n/a Disposition Approved on Date: Disposition Case Number: n/a Disposition Comment:

Disposition Date: 01 jan 1960 Disposition Event: Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1978MASERU00091
Document Source: CORE

Document Unique ID: 00 Drafter: n/a

Enclosure: n/a Executive Order: N/A Errors: N/A

Expiration: Film Number: D780016-0593 Format: TEL

From: MASERU Handling Restrictions: n/a

Image Path:

ISecure: 1

Legacy Key: link1978/newtext/t19780176/aaaacmlp.tel

Line Count: 63 Litigation Code IDs: Litigation Codes:

Litigation History:
Locator: TEXT ON-LINE, ON MICROFILM
Message ID: 2c90eae4-c288-dd11-92da-001cc4696bcc

Office: ACTION SY

Original Classification: UNCLASSIFIED
Original Handling Restrictions: n/a
Original Previous Classification: n/a
Original Previous Handling Restrictions: n/a

Page Count: 2
Previous Channel Indicators: n/a Previous Classification: n/a
Previous Handling Restrictions: n/a Reference: 78 STĂTE 5368

Retention: 0

Review Action: RELEASED, APPROVED Review Content Flags:

Review Date: 08 feb 2005 **Review Event:** Review Exemptions: n/a **Review Media Identifier:** Review Release Date: n/a

Review Release Event: n/a **Review Transfer Date:** Review Withdrawn Fields: n/a

SAS ID: 3794258 Secure: OPEN Status: NATIVE

Subject: STEEL PLATING OF TELEX RM TAGS: AFAC, ASEC, ABLD, LT, NSU

To: STATE Type: TE

vdkvgwkey: odbc://SAS/SAS.dbo.SAS_Docs/2c90eae4-c288-dd11-92da-001cc4696bcc

Review Markings: Sheryl P. Walter Declassified/Released US Department of State EO Systematic Review 20 Mar 2014

Markings: Sheryl P. Walter Declassified/Released US Department of State EO Systematic Review 20 Mar 2014